

3/24/21 Specialty Auction

Auction	Description	Bidder	Winning Bid
1	1984 Piper Navajo Mojave PA-31O-350 Reg# N454SC, Twin Piston, No logbooks., Total Time on Airframe Unknown; Seizure # 2017201500007301-012, Seized and in storage since July 2017; Last flown July 2017	Reese, Russell [11107]	\$ 65,100.00
2	2013 39 Nor-Tech 390 Sport. Hull ID# AOV37039K213, Fiberglass, Monitors not showing in photo are with the vessel and will be given to the buyer, along with personal property.	Palms Villa	\$ 235,200.00
2	37 Continental Trailer		
3	2002 Sea Ray 560 Sedan Bridge M/V "NICOLE" LOA 58' 6", HIN US-SERY0889E102	Sapman Sportswear	\$ 209,100.00
4	1996 Viking Sport Cruisers 48' Flybridge Motor Yacht M/V "NIVIA", HIN# VSC48134L596, FRP, Deep-V Hull; Information as reported January 2020	Carson, Rachelle [1016]	\$ 107,740.00
5	2005 Contender, 31 Open Fisherman, "Contender", LOA 32' 6", Hull# USJDJ31862J405, Fiberglass reinforced plastic constructed, Off white Hull, White bottom and off-white deck interior. Deep V Hull w/ 2 platform mounted gasoline Twin Yamaha 300HP Outboard Engines	Trinidad, Javier [1185]	\$ 80,110.00
6	Yamaha 60HP Motor	leguillow, luis [1092]	\$ 2,270.00
7	2003 20' Caribe DL20, RIB (Rigid Inflatable Boat), Side Console, "T/T Gail/Grace", HIN# VE-EMD-D0009L203; Information listed as reported 2/2019.	Trinidad, Javier [1185]	\$ 17,590.00
9	2 Yamaha 150 HP Outboard Motors, V-6, SN# LX150 TXRTX 400153, & SN# SX150TXRYX 052215 (2)		
9	1995 Aquasport 225 Explorer Esperanza, LOA 22 5, FRP, Reg# PR1733 AD, Hull sides & superstructure-white, Information below as reported 7/2019	Mechanic	\$ 13,000.00
11	19 Wellcraft Center Console VE: HIN: WELFUG52H596		
11	115-HP Yamaha Outboard Engine, Four Stroke, SN# 1018095	COLON RIVERA, ANDRES [1193]	\$ 10,440.00
13	1994 25' Bayliner Trophy 2502 Walk-Around equipped with a 2002 Yamaha Outboard 250 HP, 4-stroke and a 2004 Yamaha 8 HP 4-stroke outboard kicker (extra motor for emergency use. Information as reported February 2019.		
14	1999 20' Mariah 218 with a Mercruiser 5.7 Liter Inboard/Outboard; Interior upholstery is worn-out, wall coverings dirty, exposed wires, exterior gelcoat needs wax, fiberglass damage on the starboard side, stress-cracking in the gelcoat in numerous places. Hull has several scratches and gouges, metals have signs of corrosion. upholstery is sun damaged, cracked and brittle. Information as reported September 2020.		