

**10/23/19 Specialty Auction**

Auction Lot	Description	Bidder	Winning Bid
1	<p>1987 Sea Ray 340 Express Cruiser: Hull ID SERF7919A787, Length: 33'-7", Beam: 11'-11", Draft 2'-5", Cabin Cruiser, Fiberglass Construction, General Deck Layout - Anchor Slide, Trunk Cabin Top w/ Two Clear Hatches, Cockpit, Starboard Helm &amp; Console, Helm Seat, Three Engine Compartment Hatches, Center Aft Bilge Access Hatch, Green Canvas Bimini Top, Radar Arch, Port Transom Door, Fiberglass Dive Platform, Starboard Diving Ladder, Cabin Layout - Rope Locker, Full Berth w/ Storage Below, Port Hanging Locker, Starboard Storage Cabinet, Salon w/ Port Open Space, Starboard Galley, Port Food Prep Center, Starboard Head, Center Steps, Sliding Glass Entrance Door, Engines - Inboard Mercury Marine Mercruiser, 8 Cyl, 260 HP, 4400RPM, Fitted w/ Electric Start, Alternator, Heat Exchanger, Exhaust Risers, Side Exhausts &amp; Carburetor Backfire Flame Arresters, Marine Gears (M/N &amp; S/N not Visible), Fair Condition Based on Visual Examination Only, Rusted at Areas of Paint Damage &amp; Exposed Steel on Top, Exhaust Risers &amp; Forward End, Gear Boxes are Heavily Rusted, Exterior Hull - Lightly Soiled &amp; Chalky Topsides, Two Damaged Starboard Plastic Air Intake Vents, Deck - Heavily Torn Bimini Canvas Top, Missing Transom Door, Missing Passenger Seat, Heavily Soiled Helm Seat &amp; Side Panels Vinyl Upholstery, Heavily Soiled Cockpit Deck &amp; Damaged Wood Inset on Dive Platform, Cabin - Damaged Starboard Pot Light &amp; Frame, Damaged Forward Overhead Hatch Strut, Crazed Aft Overhead Hatch Glass, 1' x 4' Area of Delaminated Vinyl Headliner in Forward Cabin, Heavily Soiled Carpet, Damaged Door Mirror, Mold Stained &amp; Soiled Overhead &amp; Side Panels in the Head, Soiled Range, Missing Dinette Furniture, Missing Refrigerator &amp; Generator, Seized and in storage since August, 2018; Currently in dry dock.</p>	Fuqua, Walter [1005]	\$ 13,200.00
2	<p>Cuddy Cabin: Bahamas Registration No. NP 010018, Maker &amp; Model Unknown; Length: 24' 8", Beam: 8', Draft: 1'-10", Fiberglass Construction, Deck Layout - Forward Deck/Cabin Top, Windshield, Starboard Helm, Captain's Chair, Cockpit, Large Screw Fastened Center Deck Panel, Port Forward Bilge Access Hatch, Port &amp; Starboard Bilge Access Hatches, Center Aft Fuel Tank Access Cover, Transom Fitted w/ Basins on Both Sides &amp; Center Compartment, Aft Bench Seat, Aluminum Transom Engine Bracket, Cabin Layout - Rope Bin, Two Smoked Plexiglass Center Overhead Hatches, Vee Berth w/ Storage Below &amp; Louvered Wood Cabin Entrance Door, Folded Blue Canvas Bimini Top Cover the Forward Cockpit, Fishing Gear Consists of Rod Sockets Fitted Into Gunwale Rail, Engines: Yamaha 150 HP (S) &amp; 250 HP (P) Outboards, 6 Cyl, Port Engine M/N: 200 AETO, S/N: 757008, Starboard Engine M/N: Not Visible, S/N: Not Visible, Fitted w/ Electric Start, Alternator, Power Tilt/Trim, Sea Star Single Hydraulic Steering &amp; Three-Blade Stainless Steel Propellers, Port Engine Condition is Poor, Starboard Engine Condition is Fair, Port Engine Outboard Pump Cover is Heavily Rusted, Skeg is Moderately Chipped at Two Areas, Lower Unit is Moderately Scratched &amp; Top of the Engine Cowl is Heavily Discolored, Equipment - Ritchie Magnetic Compass, Faria Instrumentation, Engine Control, West Marine VHF 500 DSC Radiotelephone, Exterior - Clean Bottom w/ Moderately Deteriorated Bottom Paint, Cockpit - Missing Recessed Rod Racks, Missing Side Rail Pads, Missing Starboard Deck Hatch Cover, Damaged Center Aft Access Cover, Damaged Starboard Stainless Steel Handrail, Cabin - Missing Cushions, Missing Toilet, Damaged Wood Cover for the Starboard Berth Storage Compartment, Soiled &amp; Part Delaminated Blue Carpet Hull Liner &amp; Headliner, 4" Fracture on the Starboard Stepped Platform &amp; Damaged Stern Light Fixture, Seized and in storage since March 2019</p>		
3	<p>1993 Carrera 27 Open Fisherman: Hull ID: XCS27001F293, Length: 26'-8", Beam: 8', Draft: 20", Center Console, All Fiberglass Reinforced Plastic Construction, Aqua Green Hull, White Deck Interior, Two Transom Mounted Gasoline Mariners 200 2.5L Outboard Engines (S/N not visible), Two Recessed Hatches for Storage, All Aluminum Inverted Radar Arch Frame, Single Lever Controls, Ritchie Compass, Tachometers, Voltmeters, Ignition Switches w/ Shut-Off Safety Switches, Clarion Stereo, Sea Star Single Station Hydraulic Marine Steering System, Overall Fair Condition - Advanced Wear Noted on Hull &amp; Equipment, Minor to Moderate Scratches &amp; Stress Marks All Around</p>		
3	Twin Mariners 200 HP O/B Engines: S/Ns not Visible	leguillow, luis [1066]	\$ 2,520.00
4	40-HP Yamaha Outboard Engine	leguillow, luis [1066]	\$ 1,590.00
5	Enduro 40HP Yamaha Outboard Engine	Valentin, Jose [1015]	\$ 1,670.00
6	75 HP Yamaha Enduro Outboard Engine	Valentin, Jose [1015]	\$ 1,000.00
7	YAMAHA 60 HP MODEL ENDURO, NO SERIAL NUMBER PLATE	diaz, jose [1041]	\$ 290.00
8	YAMAHA 40 HP UNKNOWN MODEL Outboard, NO SERIAL NUMBER PLATE		
9	AIRCRAFT PARTS		