

**12/5/18 Vessel Sale**

<b>Auction Lot</b>	<b>Description</b>	<b>Bidder</b>	<b>Winning Bid</b>
1	1992 25' Aquasport Explorer 250 Walk Around Sport Fisherman, HID AQAN0642C292, Reg No. DL8537P, 25' Length, 9' Breadth, Draft Unknown, Fiberglass Construction, Twin Yamaha 200 HP V6 Outboards (Condition Unknown), Overall Condition of Vessel Poor	Palomino, Rafael	\$ 1,675.00
2	1994 22' Angler 220F Center Console, HIN No. ANGF2097E394, Reg. No. FL8551HV (Painted Over), Yamaha 200 HP 6 Cyl Outboard (Visual Condition Poor, Unknown if Operates), Overall Condition of Vessel is Poor	Johnson, Danny	\$ 700.00
3	1975 BAYHEAD YACHT TOURNAMENT FISHERMAN: Length: 30'07", Breadth: 11'-06", Draft: 2'-06", HIN: Not Visible, Official Number: 566069, Reg #: CT5085AN, Fiberglass Construction, General Deck Layout - Bow Roller Chock, Forward Deck w/ Center Hatch, Superstructure, Flybridge, Aluminum Framed Fiberglass Hardtop, Cockpit & 3 Access Hatches; Cabin Layout - Rope Locker, Twin Berths w/ Storage Below, Port Convertible Dinette, Starboard Galley, Starboard Head, Port & Starboard Covered Engine Compartments & Port & Starboard Twin Berths Set on the Engine Covers; Fishing Gear - Single Spreader Retractable Aluminum Outtrigger Poles, Rod Holders Fitted on the Aft Legs of the Flybridge Frame & Recessed into the Cockpit Caprail; Engines: Gasoline Inboards, V8, Fresh Water Cooled, M/N & S/N Not Visible, Rated @ 330HP @ 4000RPM, Fitted w/ Electric Start, Alternator, Heat Exchangers, Exhaust Risers & Carburetors, Marine Gears (M/N & S/N Not Visible), Engines & Gears in Fair Condition, Engines are Clean w/ no External Evidence of Fuel, Oil, Water or Exhaust Leakage, Bilges are Clean, Gear Boxes are Heavily Rusted at Random Areas of Unpainted Steel,; Equipment - Bennett Trim Tabs (Port Tab Bent & Starboard Tab Missing), Ritchie Powerdamp Magnetic Compass, VDO Instrumentation, Dual Lever Engine Controls, Raytheon R21 Pathfinder Rader, Raymarine Autohelm Autopi, Koden CVS-102 Echo Sounder (Mounting Bracket Heavily Corroded), Dytek ST500 Temperature Gauge, Speakers, Homestrand 2-Burner Alcohol/Electric Range, Danforth Anchor (Bent Fluke) w/ Attached Chain Pendant & Line Rode; Exterior Hull - Peeling Paint on the Forward & Aft Wood Spray Rails, 8" x 6" Area of Chipped Gelcoat on Starboard Aft Corner; Exterior Deck - Missing Console Door, 2 Missing Flybridge Plywood Seat Covers, 2 Damaged Flybridge Plywood Seat Covers, Damaged Starboard Flybridge Seat Forward Access Dooe, Heavily Damaged Flybridge Hardtop & Deteriorated Brightwork on all Wood Cap Rails, Trim & Ladder; Cabin - Removed Lower Panel on the Galley Cabinet & Missing Refrigerator	Galindo, Greter	\$ 525.00
4	2000 Seadoo GS: VIN: ZZN57251B000, White w/ Red Seat & Steering Column, NO TRAILER	Haiti Shipping Cargo LLC	\$ 200.00
5	(2) Yamaha 200 HP Outboard Engines, Serial No. & Year Unknown, Started as of June 2018, Missing Props	CMS	\$ 7,425.00
6	Yamaha 15 HP Outboard Motor, Model Year 2002, Condition Unknown	Marrero, Juan	\$ 500.00
7	Yamaha 30HP Outboard Motor, No. Serial No., Condition Unknown	Marrero, Juan	\$ 775.00
9	Yamaha 60 HP Enduro Outboard Motor, SERIAL #1051659, Condition Unknown	Marrero, Juan	\$ 2,225.00