

**1/20/2021 Vessel Sale**

<b>Auction</b>	<b>Description</b>	<b>Bidder</b>	<b>Winning Bid</b>
1	1978 Ta Chiao Brothers CT-54 Ketch Sailing Vessel: S/V SAILBOAT MANDALAY: 53' 6" , Hull ID# 947859, HIN# TAC540160877; Ford Lehmann Diesel Engine: No history of maintenance performed on engine. When removed from the water in June 2019, water was halfway up the engine, and showed signs of oil leaking. Rust and corrosion visible on engine. Operating condition of engine unknown. Generator shows signs of rust and condition unknown. Sail inventory is 2 - possibly a jib or a sail for mizzen mast aft; Other Condition Comments: Hull damage, doors and ports show signs of leaking, interior floor in poor condition, general wear and tear; Seized June 2019.		
5	1987 Bayliner 20' LOA, Single Yamaha LF225TURB 4-Stroke Outboard (started and ran in April 2019), Has not been started since. No maintenance history reports. Stored out of water. No electronics onboard except a VHF. Aluminum tower has some pitting and corrosion. Engine has had repairs, Interior has signs of mold/mildew, No trailer. As reported July 2020	Papajohn, Christopher [1023]	\$ 5,770.00
6	300 HP Yamaha Outboard Motors, Port, #ACF18B0760	Nguyen, Vinh [1082]	\$ 28,110.00
6	300 HP Yamaha Outboard Motors, Starboard, #AHB18A0202		
10	Wellcraft Open Fisherman CC, 37 M/V "Scarab", Hull ID: N/A, ENGINES: Twin Yamaha Outboard 300 HP, platform mounted, gasoline. Port SN#: 6CF1009116, Std SN#: 6CE1030635, Three blade stainless steel propellers. Engines hold firm on their mounts. FUEL SYSTEM: (2) 225 US gal approx., galvanized steel tank, located aft under cockpit sole & forward (Additional Tank) (2) Racor fuel filters and water separators; USCG approved fuel lines. HULL: Fiberglass reinforced plastic constructed, white & gray, DECK INTERIOR: Deep V-Hull, Fore Deck: Non skid FRP sole, recessed hatch for storage ground tackle. Recessed access cover for a fuel tank. Gray primer recoated. CENTER CONSOLE: All FRP constructed fitted with all-aluminum frame, Bimini Top secured and in fair condition. CONSOLE EQUIPMENT: (1) Stainless steel steering wheel (1) Yamaha Single Lever Controls, (1) Yamaha Electronic view panel, (1) 3 Compass, (1) DC Breakers control panel, (2) Ignition switches. AFT COCKPIT: Non-skid finished FRP sole with recessed hatches for battery compartments and misc. items, mechanical, electrical, and bilge pump. Electrical System: 12 VDC starting engines and ship service shut off safety switch. Overload protection, wiring and installations show wear but appear serviceable for marine service. BILGE PUMP: (1) Rule 2000 GPH electric automatic/manual submersible bilge pump. STEERING SYSTEM: Sea star single station hydraulic marine steering system). Starboard engine lower unit Finn broken. (2) Steering console with openings for electronics, Seized 8/30/16. As reported Feb 2018		
11	9.9 HP Yamaha Outboard Motor, SN# Detached	Moreno, Victor [1138]	\$ 390.00
12	30 HP Yamaha Outboard Motor S/N# 1098777		
13	40 HP Yamaha Outboard Motor SN# 1213766	MARTINEZ, FRANKIE [1087]	\$ 2,510.00
14	15 HP Yamaha Outboard Motor SN# 1363436	JAYS MOBILE MARINE	\$ 400.00
15	75 HP Yamaha Outboard Motor SN# Missing.	Rosado, Jairo [1126]	\$ 2,620.00
16	40 HP Yamaha Marine Outboard Motor SN# Missing	MARTINEZ, FRANKIE [1087]	\$ 900.00
17	15 HP Yamaha Marine Outboard Motor SN# 1247037	Torres, Julio [1132]	\$ 510.00
18	40 HP Yamaha Outboard Engine SN# 1239646	Mclat, JosÁ© M. [1004]	\$ 3,020.00
19	75 HP Yamaha Outboard Motor SN#: 508100	MARTINEZ, FRANKIE [1087]	\$ 1,420.00
20	15 HP Yamaha Outboard Motor SN#: Missing	Moreno, Victor [1138]	\$ 500.00
21	40 HP Yamaha Outboard Motor SN#: Detached	Mclat, JosÁ© M. [1004]	\$ 3,240.00
22	15 HP Yamaha Outboard Motor SN#: 358790	Moreno, Victor [1138]	\$ 820.00
23	60 HP Yamaha Outboard Motor, SN#: 1025557	Moreno, Victor [1138]	\$ 880.00